# PRATT & WHITNEY - ENGINE SERVICES SERVICE BULLETIN INDEX

**MANUAL PART NO. 3134285** 

## Flight-Data Acquisition Storage and Transmission System (FAST)

## APPLICABLE TO: FAST INSTALLATION DAHER MODEL TBM 700N

## Issued September 7, 2021

EXPORT CONTROL CLASSIFICATION DATE OF MARKING: (YYYY-MM-DD) 2021-09-07 BADGE: (XX#####) PW56983 Check this box if the document contains no Summarize the export classification of OR technical data. this document as instructed below. **CLASSIFICATION LOCATION U.S. REGULATION EAR ITAR** 9E991 NSR Classifications must always be P-ECCN P-USMI U.S. provided for U.S. and Outside U.S. boxes. NSR **OUTSIDE U.S.** ECCN 9E991 LOCAL REGULATION EIPA (ECL) DPA (CG) When the person completing the grid is physically Document may be DPA controlled if EIPA located outside of the U.S., the local **CANADA** NSR value starts with "2" or either ITAR box classifications must also be provided. contains any value other than "NSR".

#### WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This manual contains proprietary information of Pratt & Whitney - Engine Services, which provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of products and services, as directed therein. Neither this manual nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. The contents of this manual may be subject to export control laws. Unauthorized export or re-export of the manual, or parts thereof, is prohibited. By accepting and possessing this manual, you agree to be bound by the foregoing terms

### **PRATT & WHITNEY - ENGINE SERVICES**

#### **LOG OF REVISIONS**

REV. NO	DESCRIPTION	DATE
A	Initial Release	January 12, 2018
В	Add SB-0028	May 24, 2019
С	Update Revision of SB-0028 and WI-0062	August 28, 2019
D	Update to SB-0028	September 7, 2021

#### INTRODUCTION

This index covers all the Service Bulletins (SB's) for the FAST on the Daher Model TBM 700N aircraft by P&W Engine Services **D**iagnostics, **P**rognostics and **H**ealth **M**anagement (DPHM).

#### ⇒ To access documents listed below, open 'Attachments Panel' within PDF viewer.

SB Number	Service Bulletin Title	Revision	Revision Date
SB-0028	FAST <sup>™</sup> – MicroServer Software Upgrade to Version 3.2	С	September 7, 2021